

CAST IRON
REPAIR

In Stitches

"FIRST AID FOR METAL"

ON-SITE MACHINING
SOLUTIONS

www.castironrepair.com
www.portablemachining.com
info@castironrepair.com

Metal Locking Service Quarterly Newsletter
Spring 2010 Edition

PH: (866) FIX-IRON

Featured Job – An international chemical company contracted MLS to disassemble a 25,000 gallon stainless steel storage tank located in West Virginia and relocate it to their Buffalo, NY location. The tank was plasma cut into manageable sections that were shipped to Buffalo where they were placed, pieced together, and welded. Safety is a priority on every job but this job had special considerations with the placement of the tank in close proximity to other chemical holding tanks.



On-site Tank Assembly at FMC



In-Situ Drive Shaft Repair in Glenn Falls, NY

Dirty Work – The large gear pictured to the right is used in the processing of hot rolled steel bars. During a routine maintenance inspection, it was found to have one spoke had cracked almost completely through the cross section. MLS mobilized in a single day's time and was on-site the next. The gear was repaired at our customer's location in McDonald, OH via our metal locking technique. Our crew worked staggered shifts to help minimize the customers down time and lost production.



On-site Gear Repair in McDonald, OH

Continue to check us out on the web – www.castironrepair.com & www.portablemachining.com