


All photos show cracks and repairs touched up to facilitate photography. Actual completed repairs are difficult, if not impossible, to detect.

PERMANENT CASTING REPAIRS* without heat!



This Reel Drum for the paper industry, over 16 feet long, with 2 cracks, one of which is shown.

Repaired, without heat, and sealed against water pressure. Chalked up to photograph clearly, repaired area will be unaffected by thermal change.

***at a fraction of replacement cost**

Metal Locking Service, Inc.