


WHAT WOULD YOU DO IF THIS HAPPENED TO YOU?

**REPAIR OR REPLACEMENT
OUR SHOP OR YOURS.**



GIDDINGS & LEWIS rotary table broken during dis-assembly. When lifting to dis-assembly, customer failed to remove tie down bolts, resulting in breakage of this corner. Break was not an operational one.

**WHEN YOU NEED...
ACTION - NOT EXCUSES
CALL US!**

Corner re-fitted, critical alignment restored, then mechanically locked back into workable condition. Now as strong or stronger than before the accident, this is ready to give complete operating satisfaction.

NOTE: Area of repair is quite apparent due to "HIGH LIGHTING" to facilitate photography. It is, however, difficult if not impossible to detect repaired area upon removal of "HIGH LIGHTING" touch up.

WITHOUT THE USE OF HEAT

"FIRST AID FOR METAL"



716 / 824-4359

50 YEARS OF QUALITY WORKMANSHIP IS WHAT BUILT OUR REPUTATION...

SLIDE OF 200 TON STAMPING PRESS



Ever improving metals create demands not always met by existing equipment. We are, therefore, often asked not only to repair, but to reinforce, providing adequate strength to withstand the new demand.

Now permanently repaired by Metal Locking process, without heat, and without any post repair machining, slide is ready for full capacity operation.

LASTING DEPENDABILITY



Failure of Trunnion caused this frame breakage. Some 28 feet of fracture was permanently repaired by our cold mechanical method of repair.

An explosion caused this volute blower casing to be blown completely apart. Plant shutdown required repair in minimal time. Permanent repair was effected in 96 hours.

Customer thought this 81 1/2" herringbone gear impossible to repair without machining. Repair was accomplished with restoration of complete alignment and in excess of original strength.

"FIRST AID FOR METAL"



METAL LOCKING SERVICE inc

MLS MACHINE SHOP

68 HAYES PLACE • BUFFALO, NEW YORK 14210 • PHONE 716 / 824-4359