DEPENDABILITY AND METAL LOCKING SERVICE HAVE GONE HAND IN HAND FOR 44 YEARS

Now you can expect the same dependability from MLS Machine Shop




Above are the results of freeze breaks in a 4200 C.F.M. air compressor with a 755 horsepower motor. High-and low-pressure cylinders and heads were shattered in water jacket areas. Photo shows low-pressure head (note broken pieces in foreground) prior to repair.

Subsequent inspections revealed the necessity to remove the entire section beyond that shown here.



Ram from 800-ton Stamping Press. Badly broken and beyond repair, even for us. New ram not obtainable, and press was side lined.



Pieces were cast and machined to fit and replace the entire broken area. Sections then were metal laced and sealed against pressure, sufficient to restore the piece to full working load. Using broken ram (above) for pattern, a new and stronger ram was cast locally and machined in our shop.

Our new facility and experience were put to the test and press was returned to service.




METAL LOCKING SERVICE, INC.

68 HAYES PLACE, BUFFALO, NEW YORK 14210 Phone 716/824-4359

METAL LOCKING SERVICE, INC. ANNOUNCES

An Expanded Name for its Added Service



"An old, respected friend and a new service come together."

We have always done some machining in conjunction with our METAL LOCKING process. We feel the need is there, and we have now expanded our effort into this field. With the addition of qualified manpower and equipment, we are now in a position to do machining, welding, and babbitting for our customers and for others who have that need.

If you have had experience with the METAL LOCKING process, you know something of our track record over the past 45 years. The additional name, MLS MACHINE SHOP, is not meant to indicate a change of activity, but an expansion of our service. We are increasing our activity and hopefully increasing our list of business friends too.



MACHINE SHOP

68 HAYES PLACE • BUFFALO, NEW YORK 14210 • 716/824-4359