

"YOU REALLY CAME THROUGH FOR US.  
WE ARE COMPLETELY SATISFIED."



1962


CITY OF BUFFALO  
FIREBOAT

EDWARD M. COTTER

WITH

V-12 - 397 CATERPILLAR ENGINE


1988



BROKEN CONNECTING ROD CAUSED SEVERE DAMAGE TO ENGINE BLOCK. NEW PIECE FOR BLOCK MADE BY METAL LOCKING SERVICE INSTALLED AT FRACTION OF REPLACEMENT COST, IN MINIMAL TIME. BORE WAS MACHINED IN POSITION.

STILL OPERATING IN 1988

NO  
HEAT  
USED!



**PARTS NOT  
AVAILABLE!**

NOW SPEED REDUCER WAS DAMAGED - AND PARTS OR PRINTS NOT AVAILABLE. METAL LOCKING SERVICE CALLED UPON TO REPAIR WHERE POSSIBLE. M.L.S. MACHINE SHOP MADE NEW PARTS WHERE PARTS WERE NOT REPAIRABLE.

WE TAKE PRIDE IN OUR ABILITY TO RESTORE SEEMINGLY NON-REPAIRABLE MACHINE PARTS. WE ARE EQUALLY PROUD OF OUR MACHINE SHOP CAPABILITY.

WHEN YOU NEED....  
ACTION - NOT EXCUSES  
CALL US!


"FIRST AID FOR METAL"



**METAL LOCKING SERVICE inc**  
**MLS MACHINE SHOP**

68 HAYES PLACE • BUFFALO, NEW YORK 14210 • PHONE 716 / 824-4359

# REPAIR - AS STRONG AS NEW!



NO  
HEAT  
USED!

THE RESULT OF A BROKEN SHAFT IN A CAST IRON GEAR CASE  
FROM A BAR STRAIGHTENER FOR A PROMINENT STEEL COMPANY.



Casting 'chalked up' to show  
area of repair. Actual  
repairs are difficult to detect.

**NEW**

STEEL SECTION  
LOCKED AND LACED INTO POSITION.  
FINAL BORING RESULTED IN COMPLETE  
RE-ALIGNMENT WITH COMPANION  
BORES. PLACEMENT OF STEEL IN CAST  
IRON EFFECTS AS

**STRONG AS**

*New*  
**CONDITION!**

**OUR REPUTATION DEPENDS UPON SATISFACTORY RESULTS**

"FIRST AID FOR METAL"



**METAL LOCKING SERVICE inc**  
**MLS MACHINE SHOP**

68 HAYES PLACE • BUFFALO, NEW YORK 14210 • PHONE 716 / 824-4359