


# AND YOU THINK YOU'VE GOT FOOT PROBLEMS!



◀ 350 H.P. motor with three out of four of the mounting feet broken completely off.

Restored frame indicating repaired areas. Supplemental supports were installed in window areas and mounting alignment was re-established.



Customer was very pleased with the results!

"No problems with the re-assembly and test run".

- **NO HEAT USED!**
- **STRESS FREE REPAIR!**




**METAL LOCKING SERVICE INC.**  
**MLS MACHINE SHOP**  
68 HAYES PLACE • BUFFALO • NY • 14210 • 716.824.4359  
[www.metallocking.com](http://www.metallocking.com)

# TALK ABOUT FOOT PROBLEMS!



◀ Closeup of mounting foot area of 16 cylinder locomotive block. Both front areas have been completely torn away.



▲ Completed repair shows new sections locked and laced into position.\*



◀ Closeup indicates position of locking devices and lacing.

This repair project saved the customer a major loss of time and money.

We apply this mechanical repair concept to a variety of castings and machine parts, large & small.

Now, with over 54 years experience, we continue making mechanical repairs to a variety of castings and machine parts, large & small.

When pieces are missing, as in this example, we make up new ones.

\*Pictures are chalked to facilitate photography. Actual repair is almost impossible to detect.

FIRST AID FOR METAL™



**METAL LOCKING SERVICE INC.**

**MLS MACHINE SHOP**

68 HAYES PLACE • BUFFALO • NY • 14210 • 716.824.4359

[www.metallocking.com](http://www.metallocking.com)